




Mounting Holes:



Switch Settings

SW1.1	SW1.2			
OFF	OFF	Passthrough mode	(OUT1=PWM,	OUT2=DIR)
OFF	ON	BTS796, L298 etc.	(OUT1=RIGHT,	OUT2=LEFT)
ON	OFF	TLE5205	(OUT1=IN1,	OUT2=IN2)
ON	ON	TA7291, TA8428, etc.	(OUT1=CW,	OUT2=CCW)

Title PWM ISOLATOR/ENCODER		
Author Philip Munts Munts Technologies		
File s\products\MUNTS-0005\cad\PWM_Isolator.dsn		Document
Revision 1.0	Date 5 March 2015	Sheets 1 of 1


PWM Isolator/Encoder
J1
C1
C2
U1
U2
C3
U3
C4
J2
R1
R2
SW1
MUNTS-0005 Rev 1.0 5 March 2015
Munts Technologies
http://tech.munts.com

